

FIG, 1

Melting resin material and mixing an inert gas into the molten resin material

Injecting the mixture of the molten resin material and the inert gas into a cavity of the mold

Cooling the mold under a constant pressure

Demolding and taking the light guide plate out from the mold

FIG. 2

3.40




FIG. 3

